



10/ 650594

CofC

IFW

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee: Andre Schouten et al. Docket: 50019.256US01
Patent No.: 6,900,669 B1
Issued: May 31, 2005
Title: AREA EFFICIENT ON-CHIP TIMEOUT GENERATOR WITH LOW TEMPERATURE AND LOW SUPPLY VOLTAGE DEPENDENCY

CERTIFICATE UNDER 37 CFR 1.8:

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail, with sufficient postage, in an envelope addressed to: Certificate of Correction Branch, Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450 July 22, 2005.

By: 

Name: Leslie A. Moss

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, Virginia 22313-1450

Sir:

We are transmitting herewith the attached:

- ☒ Transmittal Sheet in duplicate containing Certificate of Mailing
- ☒ Notice of Errors in Printed Patent
- ☒ Return postcard

Please consider this a PETITION FOR EXTENSION OF TIME for a sufficient number of months to enter these papers, if appropriate. Please charge any additional fees or credit overpayment to Deposit Account No. 13-2725. A duplicate of this sheet is enclosed.

Merchant & Gould P.C.
P.O. Box 2903 Minneapolis, MN 55402-0903
612.332.5300

By: 

Name: Mark R. Hennings
Reg. No.: 48,982
MRH:lam

23552

PATENT TRADEMARK OFFICE

Certificate
AUG 17 2005
of Correction



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 6,900,669 B1 Docket: 50019.256US01
Issue Date: May 31, 2005 Patentee: Andre Schouten et al.
Title: AREA EFFICIENT ON-CHIP TIMEOUT GENERATOR WITH LOW
TEMPERATURE AND LOW SUPPLY VOLTAGE DEPENDENCY

CERTIFICATE UNDER 37 CFR 1.8:

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail, with sufficient postage, in an envelope addressed to: Certificate of Correction Branch, Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450 July 22, 2005.

By: 

Name: Leslie A. Moss

NOTICE OF ERRORS IN PRINTED PATENT

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, Virginia 22313-1450

Sir:

The following errors were noted in the above-identified issued patent:

Column 2, line 15, "arc" should be --are--.

Column 3, line 1, "to" should be --to--.

A Certificate of Correction is not believed warranted in this case, but the errors are hereby made of record for the benefit of anyone reading the file of the issued patent.

Merchant & Gould P.C.
P.O. Box 2903
Minneapolis, MN 55402-0903
612.332.5300

By: 

Name: Mark R. Hennings

Reg. No.: 48,982

MRH:lam

23552

PATENT TRADEMARK OFFICE